

Decimal Equivalents Chart

Quickly convert fractions to decimals and vice versa for industrial sealing measurements.

	1/64	.015625
1/32		.03125
	3/64	.046875
1/16		.0625
	5/64	.078125
3/32		.09375
	7/64	.109375
1/8		.125
	9/64	.140625
5/32		.15625
	11/64	.171875
3/16		.1875
	13/64	.203125
7/32		.21875
	15/64	.234375
1/4		.25
	17/64	.265625
9/32		.28125
	19/64	.296875
5/16		.3125
	21/64	.328125
11/32		.34375
	23/64	.359375
3/8		.375
	25/64	.390625
13/32		.40625
	27/64	.421875
7/16		.4375
	29/64	.453125
15/32		.46875
	31/64	.484375
1/2		.5

	33/64	.515625
17/32		.53125
	35/64	.546875
9/16		.5625
	37/64	.578125
19/32		.59375
	39/64	.609375
5/8		.625
	41/64	.640625
21/32		.65625
	43/64	.671875
11/16		.6875
	45/64	.703125
23/32		.71875
	47/64	.734375
3/4		.75
	49/64	.765625
25/32		.78125
	51/64	.796875
13/16		.8125
	53/64	.828125
27/32		.84375
	55/64	.859375
7/8		.875
	57/64	.890625
29/32		.90625
	59/64	.921875
15/16		.9375
	61/64	.953125
31/32		.96875
	63/64	.984375
1		1.