

Hospital Generator Fuel Polishing

Case Study



Problem: Hospital Needed Generator Fuel Polishing Across Multiple Storage Tanks

A healthcare facility contacted us after heavy contamination was identified in diesel fuel used for emergency generators. Sampling of the first two tanks showed significant water, particulate, and microbial growth. After seeing the condition of the first two tanks, the client had us service a 3rd tank.

- Tank 1 = 15,000 gallons
- Tank 2 = 6,000 gallons
- Tank 3 = 15,000 gallons

Total Volume of Contaminated Fuel = 36,000 gallons.



Solution: Trailer-Mounted Mobile Fuel Polishing System

PFP was able to quickly mobilize a trailer-mounted mobile fuel polishing system, allowing for multiple generator fuel tanks to be polished in a single day. This approach to fuel polishing drastically reduces downtime while simplifying on-site service.

TANK 1



TANK 2



TANK 3



 24/7, National Emergency Response

Mobile Fuel Polishing Services for Healthcare Facilities

Contact us to schedule fuel polishing services or request a site assessment.



www.PFPUSA.com

(888) 679-6645



**MULTIPLE TANKS.
ONE VISIT.**

